


BMW 5: 1HXG688

Vinnumber:	WBA5L11030D785783	Versionname:	5 TOURING 518d 136PK
First Registrationdate:	21/10/2014	Fiscalpower:	
Expertise Mileage:	185810	Power Kw:	100
Bodytype:		Body color:	Anthracite
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1515
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F	
Windows electric F	Type of Tow bar	No Tow bar
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	Headlighting Xenon	
Type of GPS	No GPS	
Type of Lining	Lining artificial leather	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/55/17/97 Y LightMetal			
Summer tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Number of charging cables (normal)	0
Number of charging cables (rapid charge)	0

Total cost ex VAT	814,00
-------------------	---------------

Bonnet, Stone chip(s), Acceptable	0,00
-----------------------------------	-------------

No pictures to display

Rearview mirror housing L, Scratch(es), Acceptable	0,00
--	-------------

No pictures to display

Alloy rim R L, Scratch(es), LI - Repair and paint (complete)	95,00
--	--------------



Bumper R, Scratch(es), LI - Repair and paint (complete) 254,16



Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



Rearview mirror housing R, Scratch(es), Acceptable 0,00

No pictures to display

Seat cover F L, Worn, Acceptable 0,00

No pictures to display

Wing R R, Scratch(es), LI - Repair and paint (complete) 369,84

