



VOLKSWAGEN Passat: 1HRA905

Vinnumber:	WVWZZZ3CZFE044771	Versionname:	PASSAT VAR Comfortline BMT 105PK
First Registrationdate:	10/09/2014	Fiscalpower:	
Expertise Mileage:	136406	Power Kw:	77
Bodytype:	Break	Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metallic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	BINNEN 10100 KM	Parking lot:	4730
Maintenance:	OK		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Sun Roof electric
Windows electric F	Panoramic roof
Windows electric R	Central consol F
Cruise Control	Luggage cover
Steering wheel multifunctional	Front parking sensors
Seats F heated	Rear parking sensors
Radio multimedia	Type of Tow bar
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining leather
Type of climate control	Autom climate control
	Tow bar fixed

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

215/55/16/93 V LightMetal			
Summer tyres:	Fr.L.	Michelin: 5 mm	Fr.R.
	Re.L.	Continental: 6 mm	Re.R.
		Michelin: 5 mm	Continental: 6 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	-----	------------	-----

Total cost ex VAT	316,96
-------------------	--------

Backrest cover F L, Scratch(es), Acceptable	0,00
---	------

No pictures to display	
------------------------	--

Rocker panel inner F R, Dent(s), Acceptable	0,00
---	------

No pictures to display	
------------------------	--

Ceiling, Stain, Cleaning	25,00
--------------------------	-------



Bumper moulding F R, Broken, E - Replace

14,40



Bumper R, Scratch(es), Acceptable

0,00

No pictures to display

Roof pillar R, Dent(s), Acceptable

0,00

No pictures to display

Window R L door, Scratch(es), 67 - Polish

0,00



Wing F R, Scratch(es), 67 - Polish

0,00



Window F R door, Scratch(es), 67 - Polish

0,00



Bumper F R, Scratch(es), It - Spot repair

115,56



Window F L door, Scratch(es), 67 - Polish

0,00



Tailgate, Scratch(es), Acceptable


0,00

No pictures to display

Rear window, Scratch(es), E - Replace

0,00





Door F R, Scratch(es), 67 - Polish

0,00



Bonnet, Dent(s), PDR - Paintless dent repair

162,00

