



CITROEN C4 PICASSO: 1LNE923

Vinnumber:	VF73DBHXTFJ816277	Versionname:	1.6 BLUEHDI 115 S/S BUSINESS GPS AUTO
First Registrationdate:	27/10/2015	Fiscalpower:	
Expertise Mileage:	176787	Power Kw:	85
Bodytype:		Body color:	White
Gearbox:	Automatic	Paint type:	Opaque
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	- 500 KM	Parking lot:	2626
Maintenance:	NOT OK		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

GPS storage	HD	Central consol F
GPS storage		Luggage cover
Windows electric F		Rear parking sensors
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Autom climate control	
Level control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	NOT OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/60/16/92 V LightMetal			
Summer tyres:	Fr.L.	Uniroyal: 2 mm	Fr.R.	Uniroyal: 2 mm
	Re.L.	Uniroyal: 4 mm	Re.R.	Uniroyal: 3 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	765,87
Central pillar L, Scratch(es), Acceptable	0,00

No pictures to display

Alloy rim F L, Scratch(es), LI - Repair and paint (complete)

95,00



Bumper Trim F, Scratch(es), E - Replace

33,91



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00



Door R L, Dent(s) and scratch(es), Acceptable

0,00



Rearview mirror housing L, Missing, Le - Replace and paint

186,40



Door F L, Scratch(es), Acceptable

0,00

No pictures to display

Engine, Maintenance, P - Check

0,00



Wing F L, Scratch(es), Acceptable

0,00

No pictures to display

Alloy rim R R, Scratch(es), LI - Repair and paint (complete)

95,00



Spoiler R, Scratch(es), Acceptable

0,00

No pictures to display

Central pillar R, Scratch(es), Acceptable

0,00

No pictures to display

Bumper F, Scratch(es), It - Spot repair

115,56



Central pillar L, Scratch(es), Acceptable

0,00

No pictures to display

Interior, Dirty, Forfeit

50,00



Bumper R, Dent(s) and scratch(es), Acceptable 0,00

No pictures to display

Alloy rim R L, Scratch(es), LI - Repair and paint (complete) 95,00

