



VOLVO V60: 1GRS222

Vinnumber:	VV1FW8481E1206195	Versionname:	V60 BRE D2 Kinetic 115PK
First Registrationdate:	10/04/2014	Fiscalpower:	
Expertise Mileage:	100854	Power Kw:	84
Bodytype:		Body color:	Dark Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3631
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Type of Tow bar	No Tow bar
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/60/16/96 H LightMetal				
Summer tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	1354,58
Roof, Chemical polution, LI - Repair and paint (complete)	481,50



Bonnet, Chemical polution, LI - Repair and paint (complete)

290,08



Wing R R, Scratch(es), Acceptable

0,00

No pictures to display

Alloy rim F R, Scratch(es), Acceptable

0,00

No pictures to display

Bumper R, Scratch(es), LI - Repair and paint (complete)

211,80



Door F L, Scratch(es), Acceptable

0,00

No pictures to display

Door R R, Dent(s), PDR - Paintless dent repair

63,00



Wing R L, Dent(s) and scratch(es), LI - Repair and paint (complete)

308,20

No pictures to display

Door F R, Scratch(es), Acceptable

0,00

No pictures to display