



FORD FOCUS CLIPPER: 1VNC986

Vinnumber:	WF06XXGCC6GK04531	Versionname:	1.5 TDCI 88KW S/S BUSINESS EDITION+
First Registrationdate:	15/06/2016	Fiscalpower:	
Expertise Mileage:	171081	Power Kw:	88
Bodytype:	Break	Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1513
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Seats electric F L	
GPS storage		Central consol F	
GPS storage	HD	Luggage cover	
Windows electric F		Front parking sensors	
Windows electric R		Rear parking sensors	
Cruise Control		Type of Tow bar	No Tow bar
Steering wheel multifunctional			
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining semi-artificial leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/55/16/91 V LightMetal				
Summer tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 7 mm	Re.R.	Michelin: 7 mm

Assistance equipment

Repair kit	No	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	1833,91
Tyre repair kit, Missing, E - Replace	210,53




Door R R, Scratch(es), LI - Repair and paint (complete)

318,35



Roof, Dent(s), LI - Repair and paint (complete)

481,50



Bumper corner R L, Scratch(es), Acceptable

0,00

No pictures to display

Alloy rim R L, Scratch(es), LI - Repair and paint (complete)

95,00



Wing R L, Scratch(es), Acceptable

0,00

No pictures to display

Bumper R, Scratch(es), Acceptable

0,00

No pictures to display

Alloy rim F L, Scratch(es), LI - Repair and paint (complete)

95,00





Rocker panel inner R R, Scratch(es), Acceptable	0,00
---	------

No pictures to display

Alloy rim F R, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Door F L, Dent(s) and scratch(es), LI - Repair and paint (complete)	318,35
---	--------



Bumper corner R R, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Bumper F, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Wing F L, Dent(s) and scratch(es), LI - Repair and paint (complete)	220,18
---	--------



Wing R R, Dent(s) and scratch(es), Acceptable	0,00
---	------

No pictures to display

Door R L, Dent(s) and scratch(es), Acceptable	0,00
---	------

No pictures to display

Wing F R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Alloy rim R R, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Windscreen, Stone chip(s), Windscreen repair	0,00
--	------

