



**VOLVO XC60: 1HJK382**

Vinnumber:	<b>YV1DZ73CDF2657401</b>	Versionname:	<b>XC60 D4 Kinetic Geartr.181PK Aut.</b>
First Registrationdate:	<b>1/08/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>33788</b>	Power Kw:	<b>133</b>
Bodytype:		Body color:	<b>Grey</b>
Gearbox:	<b>Automatic</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>1120</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD		Central consol F	
GPS storage	<b>HD</b>	Luggage cover	
GPS storage		Rear parking sensors	
Windows electric F		Type of Tow bar	<b>No Tow bar</b>
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Radio multimedia			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining leather</b>		
Type of climate control	<b>Autom climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

<b>235/65/17/104 V LightMetal</b>				
Summer tyres:	Fr.L.	<b>Continental: 4 mm</b>	Fr.R.	<b>Continental: 4 mm</b>
	Re.L.	<b>Continental: 7 mm</b>	Re.R.	<b>Continental: 7 mm</b>

**Assistance equipment**

Emergency spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
Number of charging cables (normal)	<b>0</b>		
Number of charging cables (rapid charge)	<b>0</b>		

Total cost ex VAT 1963,69

Bumper F, Scratch(es), Acceptable 0,00

No pictures to display

Bonnet, Scratch(es), LI - Repair and paint (complete) 348,09



Wing F R, Scratch(es), Acceptable 0,00

*No pictures to display*

Bumper R, Scratch(es), LI - Repair and paint (complete) 254,16



Door R L, Dent(s) and scratch(es), LI - Repair and paint (complete) 382,02



Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 369,84



Door F R, Scratch(es), Acceptable 0,00

*No pictures to display*

Tailgate, Scratch(es), LI - Repair and paint (complete) 362,02





Rocker panel inner R L, Dent(s), LI - Repair and paint (complete)

115,56



Door panel R R, Tear, E - Replace

132,00



Door F L, Scratch(es), Acceptable

0,00

No pictures to display