



VOLVO XC60: 1LFJ293			
Vinnumber:	VV1DZARC1G2825618	Versionname:	2.0 D3 2WD KINETIC
First Registrationdate:	14/09/2015	Fiscalpower:	
Expertise Mileage:	104615	Power Kw:	110
Bodytype:		Body color:	Red
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3502
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options			
Radio CD		Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Rear parking sensors	
Cruise Control		Type of Tow bar	Tow bar fixed
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear			
Summer tyres:	235/65/17/108 V LightMetal		
	Fr.L.	Fr.R.	Pirelli: 4 mm
	Re.L.	Re.R.	Pirelli: 4 mm

Assistance equipment			
Emergency spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	285,80
Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete)	211,80



Bumper F, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Roof pillar R, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Wing R L, Dent(s) and scratch(es), Acceptable	0,00
---	------

No pictures to display

Protection plate M, Deformed / Strained, E - Replace	74,00
--	-------



Alloy rim F R, Scratch(es), Acceptable	0,00
--	------

No pictures to display