



FORD S-MAX: 1JJR446

Vinnumber:	WF05XXGBWSEA11526	Versionname:	1.6 TDCI 85KW S/S TREND STYLE
First Registrationdate:	6/01/2015	Fiscalpower:	
Expertise Mileage:	107156	Power Kw:	85
Bodytype:		Body color:	Brown
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance	OK	Parking lot:	2127
Maintenance	GEEN MELDING		
Battery functioning	Yes		
Number of doors	5		
Number of seats	7		
Number head rests	7		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD		Seats electric F L
GPS storage	HD	Central consol F
GPS storage		Luggage cover
Windows electric F		Front parking sensors
Windows electric R		Rear parking sensors
Cruise Control		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

215/60/16/99 H LightMetal				
Summer tyres:	Fr.L.	Bridgestone: 3 mm	Fr.R.	Bridgestone: 6 mm
	Re.L.	Michelin: 6 mm	Re.R.	Michelin: 4 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT 859,50

Mirror side blinker L, Broken, E - Replace 31,20



Wing R L, Scratch(es), LI - Repair and paint (complete)

369,84



Ignition key, Missing, E - Replace

150,00



Wheel bolt cover R L, Missing, E - Replace

25,00



Wheel bolt cover R R, Missing, E - Replace

25,00



Door R R, Dent(s), Acceptable

0,00

No pictures to display

Rearview mirror housing L, Broken, Le - Replace and paint

213,46



Wheel bolt cover F L, Missing, E - Replace

25,00



Door F L, Dent(s), Acceptable

0,00

No pictures to display

Wing R R, Dent(s), Acceptable

0,00

No pictures to display

Wheel bolt cover F R, Missing, E - Replace

20,00



Bumper R, Scratch(es), Acceptable

0,00

No pictures to display