



VOLKSWAGEN Sharan: 1GVG486

Vinnumber:	WVWZZZ7NZEV037657	Versionname:	SHARAN Comfortline BMT 115PK
First Registrationdate:	9/05/2014	Fiscalpower:	
Expertise Mileage:	142297	Power Kw:	85
Bodytype:		Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3313
Number of doors:	5		
Number of seats:	7		
Number head rests:	7		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
Windows electric F	Front parking sensors
Windows electric R	Rear parking sensors
Cruise Control	Type of Tow bar
Steering wheel multifunctional	No Tow bar
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	215/60/16/95 H LightMetal			
Summer tyres:	Fr.L.	Continental: 4 mm	Fr.R.	Continental: 4 mm
	Re.L.	Continental: 4 mm	Re.R.	Continental: 4 mm

Assistance equipment

Number of charging cables (normal)	0
Number of charging cables (rapid charge)	0

Total cost ex VAT	0,00
Wing F L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Internal Boot Lining R, Scratch(es), Smart repair	0,00




Wing R L, Dent(s) and scratch(es), Le - Replace and paint 0,00



Bumper F, Scratch(es), LI - Repair and paint (complete) 0,00



Sliding door R, Scratch(es), LI - Repair and paint (complete) 0,00



Wheel hub cap R R, Missing, E - Replace 0,00



Wheel hub cap R L, Missing, E - Replace 0,00



Trunk lid covering R, Scratch(es), E - Replace 0,00



Sliding door L, Scratch(es), LI - Repair and paint (complete) 0,00



Tailgate, Scratch(es), LI - Repair and paint (complete)

0,00



Bumper R, Scratch(es), LI - Repair and paint (complete)

0,00



Door F L, Dent(s) and scratch(es), LI - Repair and paint (complete)

0,00



Bonnet, Chemical polution, LI - Repair and paint (complete)

0,00

