



**AUDI A3 BERLINE: 1RSD418**

|                                    |                          |              |                     |
|------------------------------------|--------------------------|--------------|---------------------|
| Vinnumber:                         | <b>WAUZZZ8V5H1056584</b> | Versionname: | <b>1.6 TDi 81kW</b> |
| First Registrationdate:            | <b>16/02/2017</b>        | Fiscalpower: |                     |
| Expertise Mileage:                 | <b>41998</b>             | Power Kw:    | <b>81</b>           |
| Bodytype:                          |                          | Body color:  | <b>Dark Brown</b>   |
| Gearbox:                           | <b>MAN 6 VIT</b>         | Paint type:  | <b>Metalic</b>      |
| Transmission:                      |                          | Rims summer: | <b>Aluminium</b>    |
| Fueltype:                          | <b>Diesel</b>            | Oil level:   | <b>OK</b>           |
| Battery functioning:               | <b>Yes</b>               | Parking lot: | <b>1212</b>         |
| Number of doors:                   | <b>4</b>                 |              |                     |
| Number of seats:                   | <b>5</b>                 |              |                     |
| Number head rests:                 | <b>5</b>                 |              |                     |
| Rims summer:                       | <b>Aluminium</b>         |              |                     |
| Category:                          | <b>Passenger Car</b>     |              |                     |
| Oil level:                         | <b>OK</b>                |              |                     |
| Registration Certificate Car (BE): | <b>Yes</b>               |              |                     |

**Options**

|                                |                              |
|--------------------------------|------------------------------|
| Radio CD                       | Central consol F             |
| Windows electric F             | Rear parking sensors         |
| Windows electric R             | Type of Tow bar              |
| Cruise Control                 | <b>No Tow bar</b>            |
| Steering wheel multifunctional |                              |
| Radio multimedia               |                              |
| Type of headlighting           | <b>Headlighting Halogen</b>  |
| Type of GPS                    | <b>GPS big screen color</b>  |
| Type of Lining                 | <b>Lining fabrics</b>        |
| Type of climate control        | <b>Autom climate control</b> |

**Limited Technical Inspection**

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                     |           | Lighting            | <b>OK</b>  |
|                     |           | Wiperblades         | <b>OK</b>  |


**Degree of wear**

|                                  |       |       |                |
|----------------------------------|-------|-------|----------------|
| <b>205/55/16/91 W LightMetal</b> |       |       |                |
| Summer tyres:                    | Fr.L. | Fr.R. | Michelin: 4 mm |
|                                  | Re.L. | Re.R. | Michelin: 6 mm |

**Assistance equipment**

|            |            |            |            |
|------------|------------|------------|------------|
| Repair kit | <b>Yes</b> | Compressor | <b>Yes</b> |
|------------|------------|------------|------------|

|   |                |
|---|----------------|
| Total cost ex VAT   | <b>1158,70</b> |
| Roof, Chemical polution, LI - Repair and paint (complete) | <b>481,50</b>  |



Alloy rim R R, Scratch(es), LI - Repair and paint (complete)

95,00



Windscreen, Stone chip(s), E - Replace

487,20



Wing R L, Scratch(es), Acceptable

0,00

*No pictures to display*

Alloy rim F L, Scratch(es), LI - Repair and paint (complete)

95,00



Bumper R, Scratch(es), 67 - Polish

0,00

*No pictures to display*