



VOLKSWAGEN UP: 1WUM828

Vinnumber:	WVWZZZAAZHD020534	Versionname:	
First Registrationdate:	5/05/2017	Fiscalpower:	
Expertise Mileage:	41238	Power Kw:	44
Bodytype:		Body color:	White
Gearbox:	MAN 5 VIT	Paint type:	Opaque
Transmission:	Front	Rims summer:	Steel
Fueltype:	Petrol	Oil level:	OK
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	4		
Number head rests:	2		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	No		

Options

Radio CD		Luggage cover	
Windows electric F		Type of Tow bar	No Tow bar
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	No GPS		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

165/70/14/81 T Steel				
Summer tyres:	Fr.L.	Other: 3 mm	Fr.R.	Other: 3 mm
	Re.L.	Other: 5 mm	Re.R.	Other: 5 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT 2455,28

Registration Document, Missing, E - Replace 150,00

No pictures to display

Instruction book, Missing, E - Replace 0,00

No pictures to display

Certificate Of Conformity, Missing, E - Replace 150,00

No pictures to display

Bumper F, Scratch(es), Le - Replace and paint 607,20



Wheel cover R R, Scratch(es), E - Replace

24,00



Bumper R, Scratch(es), LI - Repair and paint (complete)

169,44



Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete)

246,56



Wheel cover R L, Scratch(es), E - Replace

24,00



Door F R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Door R L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Wing R L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Wheel cover F R, Scratch(es), E - Replace	24,00



Bonnet, Dent(s) and scratch(es), Le - Replace and paint	827,76
---	--------





Floor covering F L, Hole, Smart repair 64,32



Rearview mirror R complete, Broken, E - Replace 144,00



Door F L, Scratch(es), Acceptable 0,00

No pictures to display

Wheel cover F L, Scratch(es), E - Replace 24,00

