


**FORD MONDEO CLIPPER: 1KBJ287**

Vinnumber:	<b>WF0FXXWPCFFK01198</b>	Versionname:	<b>2.0 TDCI 110KW S/S ECONETIC BUSINESS ED+</b>
First Registrationdate:	<b>25/03/2015</b>	Fiscalpower:	<b>110</b>
Expertise Mileage:	<b>91100</b>	Power Kw:	<b>110</b>
Bodytype:	<b>Break</b>	Body color:	<b>Grey</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>OK</b>	Parking lot:	<b>3807</b>
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD		Seats electric F L
GPS storage	<b>HD</b>	Central consol F
GPS storage		Luggage cover
Windows electric F		Front parking sensors
Windows electric R		Rear parking sensors
Cruise Control		
Steering wheel multifunctional		
Seats F heated		
Type of headlighting	<b>Headlighting Halogen</b>	
Type of GPS	<b>GPS big screen color</b>	
Type of Lining	<b>Lining leather</b>	
Type of climate control	<b>Autom climate control</b>	

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

215/60/16/95 V LightMetal				
Summer tyres:	Fr.L.	<b>Bridgestone: 4 mm</b>	Fr.R.	<b>Bridgestone: 4 mm</b>
	Re.L.	<b>Bridgestone: 6 mm</b>	Re.R.	<b>Bridgestone: 6 mm</b>

**Assistance equipment**

Spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
-------------	------------	------	------------

Total cost ex VAT 1060,02

Door F R, Scratch(es), Acceptable 0,00

*No pictures to display*

Window handle F L, Crack, E - Replace 45,10



Wing R R, Dent(s) and scratch(es), LI - Repair and paint (partial)

163,56



Rearview mirror housing L, Bad repair, LI - Repair and paint (complete)

115,56



Wing R R, Scratch(es), Acceptable

0,00

No pictures to display

Door F L, Bad repair, LI - Repair and paint (partial)

115,56



Sill outer L, Scratch(es), It - Spot repair

115,56



Rearview mirror housing R, Bad repair, LI - Repair and paint (complete)

115,56



Bumper F, Scratch(es), Acceptable

0,00

No pictures to display

Door R L, Bad repair, LI - Repair and paint (partial)

115,56



Rocker panel inner F L, Scratch(es), Forfeit

115,56



Roof pillar R, Scratch(es), Acceptable

0,00

No pictures to display

Bonnet, Scratch(es), Acceptable

0,00

No pictures to display

Roof, Dent(s), PDR - Paintless dent repair

63,00



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00



Bumper R, Scratch(es), Acceptable

0,00

*No pictures to display*

Wing R L, Dent(s), Acceptable

0,00

*No pictures to display*