


RENAULT Kangoo Express: 1EUM045

Vinnnumber:	VF1FW15H548657343	Versionname:	KANGOO EXPR.B/F MAXI Gr.Confort FAP 90PK
First Registrationdate:	25/03/2013	Fiscalpower:	
Expertise Mileage:	113831	Power Kw:	66
Bodytype:		Body color:	Grey
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	2620
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	2		
Number head rests:	2		
Rims summer:	Steel		
Category:	Light Commercial Vehicle		
Oil level:	OK		

Options

Radio CD		Rear parking sensors	
Windows electric F		Type of Tow bar	Tow bar fixed
Type of headlighting	Headlighting Halogen		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	195/65/15/92 H Steel			
Summer tyres:	Fr.L.	Semperit: 5 mm	Fr.R.	Semperit: 5 mm
	Re.L.	Semperit: 6 mm	Re.R.	Semperit: 6 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	2447,97
-------------------	---------

Wing R L, Scratch(es), LI - Repair and paint (complete)	231,15
---------------------------------------------------------	--------



Sill outer R, Dent(s), LI - Repair and paint (complete)	280,88
---------------------------------------------------------	--------



Wing R R, Dent(s), LI - Repair and paint (complete)

327,15



Seat cover F L, Tear, E - Replace

300,00



Rearview mirror housing L, Scratch(es), Acceptable

0,00

No pictures to display

Roof, Dent(s), LI - Repair and paint (complete)

361,13



Wing trim R L, Scratch(es), Acceptable

0,00

No pictures to display

Sill outer L, Dent(s), It - Spot repair

115,56



Trunk door R L, Dent(s), PDR - Paintless dent repair

63,00



Bumper R, Scratch(es), Smart repair

110,64



Wing F R, Scratch(es), Acceptable

0,00

No pictures to display

Rearlight L, Scratch(es), E - Replace

91,50



Rearview mirror housing R, Scratch(es), Smart repair

110,64



Bonnet, Dent(s), LI - Repair and paint (complete)

217,56



Door F R, Dent(s), LI - Repair and paint (complete)

238,76

