



TOYOTA AURIS BREAK: 1ULX698

Vinnumber:	SB1Z53JE90E427858	Versionname:	
First Registrationdate:	11/06/2018	Fiscalpower:	73
Expertise Mileage:	18893	Power Kw:	White
Bodytype:	Break	Body color:	Metalic
Gearbox:	Automatic	Paint type:	Aluminium
Transmission:		Rims summer:	OK
Fueltype:	Hybrid Petrol	Oil level:	2105
Battery functioning:	Yes	Parking lot:	
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Windows electric F	Central consol F
Windows electric R	Luggage cover
Cruise Control	Type of Tow bar
Steering wheel multifunctional	No Tow bar
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	NOT OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

225/45/17/91 W LightMetal				
Summer tyres:	Fr.L.	Dunlop: 6 mm	Fr.R.	Dunlop: 6 mm
	Re.L.	Dunlop: 7 mm	Re.R.	Dunlop: 7 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	1016,80
Alloy rim R R polished, Scratch(es), LI - Repair and paint (complete)	95,00



Wing R L, Dent(s) and scratch(es), LI - Repair and paint (complete)	308,20
---	---------------



Bumper F, Scratch(es), LI - Repair and paint (complete) 211,80



Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete) 95,00



Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete) 211,80



Alloy rim F L polished, Scratch(es), LI - Repair and paint (complete) 95,00

