


**SKODA Octavia: 1GXC595**

|                                    |                          |              |                                     |
|------------------------------------|--------------------------|--------------|-------------------------------------|
| Vinnumber:                         | <b>TMBJG9NE7E0223054</b> | Versionname: | <b>OCTAVIA COMBI Ambition 105PK</b> |
| First Registrationdate:            | <b>23/05/2014</b>        | Fiscalpower: |                                     |
| Expertise Mileage:                 | <b>99142</b>             | Power Kw:    | <b>77</b>                           |
| Bodytype:                          |                          | Body color:  | <b>Blue</b>                         |
| Gearbox:                           | <b>MAN 5 VIT</b>         | Paint type:  | <b>Metalic</b>                      |
| Transmission:                      | <b>Front</b>             | Rims summer: | <b>Aluminium</b>                    |
| Fueltype:                          | <b>Diesel</b>            | Oil level:   | <b>OK</b>                           |
| Battery functioning:               | <b>Yes</b>               | Parking lot: | <b>3114</b>                         |
| Number of doors:                   | <b>5</b>                 |              |                                     |
| Number of seats:                   | <b>5</b>                 |              |                                     |
| Number head rests:                 | <b>5</b>                 |              |                                     |
| Rims summer:                       | <b>Aluminium</b>         |              |                                     |
| Category:                          | <b>Passenger Car</b>     |              |                                     |
| Oil level:                         | <b>OK</b>                |              |                                     |
| Registration Certificate Car (BE): | <b>Yes</b>               |              |                                     |

**Options**

|                                |                              |
|--------------------------------|------------------------------|
| Windows electric F             | Central consol F             |
| Windows electric R             | Luggage cover                |
| Cruise Control                 | Front parking sensors        |
| Steering wheel multifunctional | Rear parking sensors         |
| Seats F heated                 | Type of Tow bar              |
| Radio multimedia               | <b>No Tow bar</b>            |
| Type of headlighting           | <b>Headlighting Xenon</b>    |
| Type of GPS                    | <b>GPS big screen color</b>  |
| Type of Lining                 | <b>Lining fabrics</b>        |
| Type of climate control        | <b>Autom climate control</b> |

**Limited Technical Inspection**

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                     |           | Lighting            | <b>OK</b>  |
|                     |           | Wiperblades         | <b>OK</b>  |

**Degree of wear**

|               |                                  |                          |       |                          |
|---------------|----------------------------------|--------------------------|-------|--------------------------|
|               | <b>205/55/16/91 V LightMetal</b> |                          |       |                          |
| Summer tyres: | Fr.L.                            | <b>Continental: 5 mm</b> | Fr.R. | <b>Continental: 5 mm</b> |
|               | Re.L.                            | <b>Continental: 5 mm</b> | Re.R. | <b>Continental: 5 mm</b> |

**Assistance equipment**

|  |            |            |            |
|--|------------|------------|------------|
| Repair kit                               | <b>Yes</b> | Compressor | <b>Yes</b> |
| Number of charging cables (normal)       | <b>0</b>   |            |            |
| Number of charging cables (rapid charge) | <b>0</b>   |            |            |

|                                   |      |
|-----------------------------------|------|
| Total cost ex VAT                 | 0,00 |
| Bumper R, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i>     |      |
| Wing R L, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i>     |      |
| Bumper F, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i>     |      |

