



VOLVO V40 CROSS COUNTRY: 1KLX319

Vinnumber:	YV1MZ74L1G2091175	Versionname:	1.6 D2 KINETIC
First Registrationdate:	29/05/2015	Fiscalpower:	
Expertise Mileage:	107212	Power Kw:	84
Bodytype:	Hatchback	Body color:	Blue
Gearbox:	MAN 6 VIT	Paint type:	Metallic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	3404
Maintenance:	OVER 20905 KM		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Windows electric F	Central consol F
Windows electric R	Rear parking sensors
Cruise Control	
Steering wheel multifunctional	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/50/16/92 W LightMetal			
Summer tyres:	Fr.L.	Bridgestone: 5 mm	Fr.R.	Bridgestone: 5 mm
	Re.L.	Bridgestone: 7 mm	Re.R.	Bridgestone: 7 mm

Assistance equipment

Compressor	Yes
------------	------------

Total cost ex VAT	713,09
Alloy rim R R, Scratch(es), LI - Repair and paint (complete)	308,20





Seat cover R, Stain, Cleaning

50,00



Bumper R, Scratch(es), Smart repair

110,64



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00



Luggage space cover, Dirty, Cleaning

25,00



Rearview mirror housing R, Missing, E - Replace

29,25



Alloy rim F L, Scratch(es), LI - Repair and paint (complete)

95,00

