



**VOLKSWAGEN Passat: 1JNA097**

Vinnumber:	<b>WVWZZZ3CZFE430172</b>	Versionname:	<b>PASSAT VAR Comfortline 150PK</b>
First Registrationdate:	<b>20/01/2015</b>	Fiscalpower:	
Expertise Mileage:	<b>117527</b>	Power Kw:	<b>110</b>
Bodytype:	<b>Break</b>	Body color:	<b>Black</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>2704</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD		Sun Roof electric	
GPS storage	<b>HD</b>	Panoramic roof	
GPS storage		Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Type of Tow bar	<b>Tow bar fixed</b>
Radio multimedia			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining fabrics</b>		
Type of climate control	<b>Autom climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

<b>215/60/16/99 H LightMetal</b>				
Winter tyres:	Fr.L.	<b>Bridgestone: 3 mm</b>	Fr.R.	<b>Bridgestone: 3 mm</b>
	Re.L.	<b>Goodyear: 6 mm</b>	Re.R.	<b>Goodyear: 6 mm</b>

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
Number of charging cables (normal)	<b>0</b>		
Number of charging cables (rapid charge)	<b>0</b>		

Total cost ex VAT 569,40

Wing R R, Dent(s) and scratch(es), Acceptable 0,00

No pictures to display

Wing F L, Dent(s), Acceptable 0,00

No pictures to display



Door R R, Dent(s) and scratch(es), Acceptable

0,00

*No pictures to display*

Door F L, Scratch(es), Acceptable

0,00

*No pictures to display*

Door F R, Scratch(es), Acceptable

0,00

*No pictures to display*

Bonnet, Dent(s), Acceptable

0,00

*No pictures to display*

Door R L, Dent(s) and scratch(es), Acceptable

0,00

*No pictures to display*

Alloy rim R L, Scratch(es), Acceptable

0,00

*No pictures to display*

Bumper R, Scratch(es), LI - Repair and paint (complete)

211,80



Windscreen, Repaired, Acceptable

0,00



Tailgate, Dent(s), PDR - Paintless dent repair

63,00



Bumper F, Scratch(es), LI - Repair and paint (complete)

211,80



Rearview mirror housing L, Scratch(es), Acceptable

0,00

*No pictures to display*