


**AUDI A3: 1GUR676**

Vinnumber:	<b>WAUZZZ8V8EA164726</b>	Versionname:	<b>A3 SB Ambiente S-tr.105PK Aut.</b>
First Registrationdate:	<b>6/05/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>94790</b>	Power Kw:	<b>77</b>
Bodytype:	<b>Hatchback</b>	Body color:	<b>Brown</b>
Gearbox:	<b>Automatic</b>	Paint type:	<b>Metallic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>3813</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD		Sun Roof electric	
GPS storage	<b>SD</b>	Central consol F	
GPS storage		Luggage cover	
Windows electric F		Front parking sensors	
Windows electric R		Rear parking sensors	
Cruise Control		Type of Tow bar	<b>No Tow bar</b>
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining semi-artificial leather</b>		
Type of climate control	<b>Autom climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

<b>205/55/16/91 W LightMetal</b>				
Summer tyres:	Fr.L.	<b>Bridgestone: 6 mm</b>	Fr.R.	<b>Bridgestone: 6 mm</b>
	Re.L.	<b>Continental: 5 mm</b>	Re.R.	<b>Continental: 5 mm</b>

**Assistance equipment**


Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
Number of charging cables (normal)	<b>0</b>		
Number of charging cables (rapid charge)	<b>0</b>		

Total cost ex VAT	1443,56
Alloy rim F L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Seat cover F L, Worn, Acceptable	0,00



Tailgate, Dent(s) and scratch(es), LI - Repair and paint (complete)

301,68



Door F L, Dent(s) and scratch(es), LI - Repair and paint (complete)

318,35



Door R L, Dent(s) and scratch(es), Acceptable

0,00

No pictures to display

Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete)

318,35



Wing F R, Scratch(es), Acceptable

0,00

No pictures to display

Bumper F, Scratch(es), Acceptable

0,00

No pictures to display



Alloy rim R R, Scratch(es), LI - Repair and paint (complete)

95,00



Rear window, Scratch(es), E - Replace

0,00



Door F R, Scratch(es), Acceptable

0,00

No pictures to display

Bumper R, Scratch(es), Acceptable

0,00

No pictures to display

Bonnet, Dent(s), Acceptable

0,00

No pictures to display

Roof, Dent(s), Acceptable

0,00

No pictures to display

Wing F L, Dent(s) and scratch(es), LI - Repair and paint (complete)

220,18



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00





Sill outer R, Scratch(es), Acceptable	0,00
---------------------------------------	------

No pictures to display

Alloy rim R L, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------

