



<b>BMW 1: 1HSK671</b>			
Vinnumber:	<b>WBA1C91080P695931</b>	Versionname:	<b>1 HATCH 116d Eff.Dyn.Ed. 116PK</b>
First Registrationdate:	<b>22/09/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>40492</b>	Power Kw:	<b>85</b>
Bodytype:		Body color:	<b>Grey</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Back</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>2707</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

<b>Options</b>			
Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	<b>HD</b>	Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	<b>No Tow bar</b>
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Radio multimedia			
Type of headlighting	<b>Headlighting Xenon</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining fabrics</b>		
Type of climate control	<b>Autom climate control</b>		

<b>Limited Technical Inspection</b>			
Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

<b>Degree of wear</b>				
	<b>205/55/16/91 W LightMetal</b>			
Summer tyres:	Fr.L.	<b>Michelin: 5 mm</b>	Fr.R.	<b>Michelin: 5 mm</b>
	Re.L.	<b>Michelin: 6 mm</b>	Re.R.	<b>Michelin: 6 mm</b>

<b>Assistance equipment</b>			
Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
Number of charging cables (normal)	<b>0</b>		
Number of charging cables (rapid charge)	<b>0</b>		

<b>Total cost ex VAT</b>	<b>1009,00</b>
<b>Door F L, Scratch(es), Acceptable</b>	<b>0,00</b>
<i>No pictures to display</i>	
<b>Inner door handle R L, Scratch(es), E - Replace</b>	<b>36,00</b>



Wing R R, Dent(s), PDR - Paintless dent repair	63,00
--	-------



Alloy rim R R, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Protection plate M, Deformed / Strained, E - Replace	74,00
--	-------



Wing R L, Dent(s) and scratch(es), LI - Repair and paint (complete)	308,20
---	--------



Door F R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Tailgate, Dent(s), Acceptable	0,00
-------------------------------	------

No pictures to display

Door R R, Dent(s), PDR - Paintless dent repair	63,00
--	-------



Door panel R R, Scratch(es), Acceptable	0,00
---	------

No pictures to display

Bumper F, Dent(s) and scratch(es), Acceptable	0,00
---	------

No pictures to display

Alloy rim R L, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Bumper R, Scratch(es), LI - Repair and paint (complete)

211,80



Door R L, Dent(s), PDR - Paintless dent repair

63,00



Alloy rim F R, Scratch(es), Acceptable

0,00

No pictures to display

Windscreen, Stone chip(s), Acceptable

0,00

No pictures to display