



AUDI A6: 1HRA906

Vinnumber:	WAUZZZ4G9EN110481	Versionname:	A6 AVANT 136PK
First Registrationdate:	10/09/2014	Fiscalpower:	
Expertise Mileage:	101833	Power Kw:	100
Bodytype:	Break	Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3305
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	HD	Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	Tow bar removable
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting Xenon		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK


Degree of wear

225/60/16/98 Y LightMetal				
Summer tyres:	Fr.L.	Firestone: 4 mm	Fr.R.	Firestone: 4 mm
	Re.L.	Firestone: 5 mm	Re.R.	Firestone: 5 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	624,00
Rear window, Scratch(es), E - Replace	0,00



Alloy rim R R, Scratch(es), Acceptable 0,00

No pictures to display

Roof, Chemical polution, 67 - Polish 0,00

No pictures to display

Bumper F, Scratch(es), LI - Repair and paint (complete) 254,16



Alloy rim F R, Scratch(es), Acceptable 0,00

No pictures to display

Bumper R, Scratch(es), Acceptable 0,00

No pictures to display

Rearview mirror housing L, Scratch(es), Acceptable 0,00

No pictures to display

Bonnet, Stone chip(s), Acceptable 0,00

No pictures to display

Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 369,84



Door R L, Scratch(es), Acceptable 0,00

No pictures to display