



FORD FIESTA: 1HPN030

| | | | |
|------------------------------------|--------------------------|--------------|------------------|
| Vinnumber: | WF0JXXGAHJJS14941 | Versionname: | |
| First Registrationdate: | 19/03/2018 | Fiscalpower: | |
| Expertise Mileage: | 22164 | Power Kw: | 63 |
| Bodytype: | Hatchback | Body color: | Dark Grey |
| Gearbox: | MAN 6 VIT | Paint type: | Metalic |
| Transmission: | Front | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | 4325 |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

Options

| | | | |
|--------------------------------|-------------------------------|----------------------|-------------------|
| Windows electric F | | Luggage cover | |
| Cruise Control | | Rear parking sensors | |
| Steering wheel multifunctional | | Type of Tow bar | No Tow bar |
| Radio multimedia | | | |
| Type of headlighting | Headlighting Halogen | | |
| Type of GPS | No GPS | | |
| Type of Lining | Lining fabrics | | |
| Type of climate control | Manual climate control | | |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|---------------|----------------------------------|-----------------------|-------|-----------------------|
| Winter tyres: | 195/60/15/88 V LightMetal | | | |
| | Fr.L. | Goodyear: 3 mm | Fr.R. | Goodyear: 3 mm |
| | Re.L. | Goodyear: 7 mm | Re.R. | Goodyear: 7 mm |

Assistance equipment

| | | | |
|--|------------|------------|------------|
| Repair kit | Yes | Compressor | Yes |
| Number of charging cables (normal) | 0 | | |
| Number of charging cables (rapid charge) | 0 | | |

| | |
|----------------------------------|---------------|
| Total cost ex VAT | 150,00 |
| Door F L, Bad repair, Acceptable | 0,00 |





Windscreen, Stone chip(s), Acceptable 0,00

No pictures to display

Wing F L, Bad repair, Acceptable 0,00



Bumper F, Scratch(es), Acceptable 0,00

No pictures to display

Ignition key, Missing, E - Replace 150,00

No pictures to display

Bonnet, Bad repair, Acceptable 0,00

