



BMW 5 BERLINE: 1LFX924

Vinnumber:	WBA5E31090G040766	Versionname:	2.0 518D (100KW)
First Registrationdate:	17/09/2015	Fiscalpower:	
Expertise Mileage:	128485	Power Kw:	100
Bodytype:		Body color:	Grey
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	4412
Maintenance:	5000		
Maintenance:	MEI 2021		
Battery functioning:	Yes		
Number of doors:	4		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage	HD	Front parking sensors	
GPS storage		Rear parking sensors	
Windows electric F		Type of Tow bar	Tow bar removable
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting Xenon		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

225/55/17/97 Y LightMetal				
Summer tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Total cost ex VAT			584,72
Door seal R L, Broken, E - Replace			60,00



Door frame F R, Scratch(es), Acceptable	0,00
---	------

No pictures to display

Sill trim R, Scratch(es), It - Spot repair	115,56
--	--------



Bumper R, Repaired, Acceptable	0,00
--------------------------------	------

No pictures to display

Tailgate, Repaired, Acceptable	0,00
--------------------------------	------

No pictures to display

Centre console, Scratch(es), Acceptable	0,00
---	------

No pictures to display

Armrest R M, Scratch(es), Acceptable	0,00
--------------------------------------	------

No pictures to display

Outer backrest protection L, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Bumper F, Dent(s) and scratch(es), LI - Repair and paint (complete)	254,16
---	--------



Bodywork, Not original part, Acceptable	0,00
---	------

No pictures to display

Maintenance book, Missing, Acceptable	0,00
---------------------------------------	------

No pictures to display

Alloy rim R L, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Door seal R R, Broken, E - Replace	60,00
------------------------------------	-------



License plate F, Deformed / Strained, E - Replace	0,00
---	------



Outer backrest protection R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Door F L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Seat F L compl, Worn, Acceptable	0,00
<i>No pictures to display</i>	
Door R R, Dent(s) and scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Door frame R R, Dent(s), Acceptable	0,00
<i>No pictures to display</i>	
Rear bulkhead lining, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Roof, Bad repair, Acceptable	0,00

