



|                                    |                          |              |                             |
|------------------------------------|--------------------------|--------------|-----------------------------|
| <b>BMW 5: 1HHP971</b>              |                          |              |                             |
| Vinnumber:                         | <b>WBA5L31060D677573</b> | Versionname: | <b>5 TOURING 520d 163PK</b> |
| First Registrationdate:            | <b>25/07/2014</b>        | Fiscalpower: |                             |
| Expertise Mileage:                 | <b>153449</b>            | Power Kw:    | <b>120</b>                  |
| Bodytype:                          |                          | Body color:  | <b>Grey</b>                 |
| Gearbox:                           | <b>MAN 6 VIT</b>         | Paint type:  | <b>Metalic</b>              |
| Transmission:                      | <b>Back</b>              | Rims summer: | <b>Aluminium</b>            |
| Fueltype:                          | <b>Diesel</b>            | Oil level:   | <b>OK</b>                   |
| Battery functioning:               | <b>Yes</b>               | Parking lot: | <b>4415</b>                 |
| Number of doors:                   | <b>5</b>                 |              |                             |
| Number of seats:                   | <b>5</b>                 |              |                             |
| Number head rests:                 | <b>5</b>                 |              |                             |
| Rims summer:                       | <b>Aluminium</b>         |              |                             |
| Category:                          | <b>Passenger Car</b>     |              |                             |
| Oil level:                         | <b>OK</b>                |              |                             |
| Registration Certificate Car (BE): | <b>Yes</b>               |              |                             |

|                                |                                  |                       |                   |
|--------------------------------|----------------------------------|-----------------------|-------------------|
| <b>Options</b>                 |                                  |                       |                   |
| Radio CD                       |                                  | Central consol F      |                   |
| GPS storage                    |                                  | Luggage cover         |                   |
| GPS storage                    | <b>HD</b>                        | Front parking sensors |                   |
| Windows electric F             |                                  | Rear parking sensors  |                   |
| Windows electric R             |                                  | Type of Tow bar       | <b>No Tow bar</b> |
| Cruise Control                 |                                  |                       |                   |
| Steering wheel multifunctional |                                  |                       |                   |
| Radio multimedia               |                                  |                       |                   |
| Type of headlighting           | <b>Headlighting Xenon</b>        |                       |                   |
| Type of GPS                    | <b>GPS big screen color</b>      |                       |                   |
| Type of Lining                 | <b>Lining artificial leather</b> |                       |                   |
| Type of climate control        | <b>Autom climate control</b>     |                       |                   |

|                                     |           |                     |            |
|-------------------------------------|-----------|---------------------|------------|
| <b>Limited Technical Inspection</b> |           |                     |            |
| Airco functioning                   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile                  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position                       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime                 | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass                        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake                           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                                     |           | Lighting            | <b>OK</b>  |
|                                     |           | Wiperblades         | <b>OK</b>  |

|                       |                                  |                       |       |                       |
|-----------------------|----------------------------------|-----------------------|-------|-----------------------|
| <b>Degree of wear</b> |                                  |                       |       |                       |
|                       | <b>225/55/17/97 Y LightMetal</b> |                       |       |                       |
| Summer tyres:         | Fr.L.                            | <b>Michelin: 3 mm</b> | Fr.R. | <b>Michelin: 3 mm</b> |
|                       | Re.L.                            | <b>Michelin: 4 mm</b> | Re.R. | <b>Michelin: 4 mm</b> |

|  |            |            |            |
|--|------------|------------|------------|
| <b>Assistance equipment</b>              |            |            |            |
| Repair kit                               | <b>Yes</b> | Compressor | <b>Yes</b> |
| Number of charging cables (normal)       | <b>0</b>   |            |            |
| Number of charging cables (rapid charge) | <b>0</b>   |            |            |

Total cost ex VAT 1152,53

Door F R, Scratch(es), Acceptable 0,00

No pictures to display

Door F L, Dent(s), Acceptable 0,00

No pictures to display

|  |        |
|--|--------|
| Door F L, Scratch(es), Acceptable                            | 0,00   |
| <i>No pictures to display</i>                                |        |
| Wing F R, Scratch(es), LI - Repair and paint (complete)      | 264,21 |
|  |        |
| Wing R L, Dent(s), Acceptable                                | 0,00   |
| <i>No pictures to display</i>                                |        |
| Alloy rim R L, Scratch(es), LI - Repair and paint (complete) | 95,00  |
|  |        |
| Rearview mirror housing R, Scratch(es), Acceptable           | 0,00   |
| <i>No pictures to display</i>                                |        |
| Bumper R, Scratch(es), LI - Repair and paint (complete)      | 254,16 |
|  |        |
| Alloy rim R R, Scratch(es), LI - Repair and paint (complete) | 95,00  |
|  |        |
| Alloy rim F L, Scratch(es), LI - Repair and paint (complete) | 95,00  |
|  |        |
| Bumper F, Scratch(es), LI - Repair and paint (complete)      | 254,16 |
|  |        |
| Alloy rim F R, Scratch(es), LI - Repair and paint (complete) | 95,00  |
|  |        |