



MERCEDES CLA SHOOTING BRAKE: 1LFR339

| | | | |
|------------------------------------|--------------------------|--------------|---|
| Vinnumber: | WDD1179081N183344 | Versionname: | 2.1 CLA 200 D URBAN SHOOTING BRAKE |
| First Registrationdate: | 15/09/2015 | Fiscalpower: | |
| Expertise Mileage: | 193536 | Power Kw: | 100 |
| Bodytype: | | Body color: | Black |
| Gearbox: | Automatic | Paint type: | Metalic |
| Transmission: | Front | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | 4221 |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 1 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

Options

| | | | |
|--------------------------------|----------------------------------|-----------------------|----------------------|
| Radio CD | | Seats electric F L | |
| GPS storage | SD | Central consol F | |
| GPS storage | | Front parking sensors | |
| Windows electric F | | Rear parking sensors | |
| Windows electric R | | Type of Tow bar | Tow bar fixed |
| Cruise Control | | | |
| Steering wheel multifunctional | | | |
| Radio multimedia | | | |
| Type of headlighting | Headlighting Xenon | | |
| Type of GPS | GPS big screen color | | |
| Type of Lining | Lining artificial leather | | |
| Type of climate control | Manual climate control | | |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|----------------------------------|-------|--------------------------|-------|--------------------------|
| 225/40/18/92 Y LightMetal | | | | |
| Summer tyres: | Fr.L. | Continental: 4 mm | Fr.R. | Continental: 4 mm |
| | Re.L. | Continental: 6 mm | Re.R. | Continental: 6 mm |

Assistance equipment

| | | | |
|--|-----------|------------|-----------|
| Repair kit | No | Compressor | No |
| Number of charging cables (normal) | 0 | | |
| Number of charging cables (rapid charge) | 0 | | |

Total cost ex VAT 2337,98

Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete) 95,00



Bumper F, Scratch(es), LI - Repair and paint (complete)

211,80



Door R L, Dent(s) and scratch(es), LI - Repair and paint (complete)

318,35



Alloy rim R L polished, Scratch(es), LI - Repair and paint (complete)

95,00



Bumper R, Scratch(es), Acceptable

0,00

No pictures to display

Sill outer R, Scratch(es), 67 - Polish

0,00

No pictures to display

Tyre repair kit, Missing, E - Replace

210,53



Door F L, Dent(s) and scratch(es), LI - Repair and paint (complete)

318,35



Windscreen, Stone chip(s), Windscreen repair 0,00



Roof, Scratch(es), 67 - Polish 0,00

No pictures to display

Luggage space cover, Missing, E - Replace 240,00



Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 318,35



Alloy rim F L polished, Scratch(es), LI - Repair and paint (complete) 95,00



Seat cover F L, Worn, Acceptable 0,00



Compressor, Missing, E - Replace 0,00



| | |
|---|-------|
| Door F R, Dent(s) and scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Bumper grille, Broken, E - Replace | 32,40 |



| | |
|---|--------|
| Wing R R, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Bonnet, Stone chip(s), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Wing R L, Dent(s) and scratch(es), LI - Repair and paint (complete) | 308,20 |



| | |
|---|-------|
| Alloy rim R R polished, Scratch(es), LI - Repair and paint (complete) | 95,00 |
|---|-------|

