


PEUGEOT 308: 1HRH949

Vinnumber:	VF3LC9HPAES197236	Versionname:	308 SW Active 92PK
First Registrationdate:	12/09/2014	Fiscalpower:	
Expertise Mileage:	162637	Power Kw:	68
Bodytype:		Body color:	Brown
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2411
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Panoramic roof	
Windows electric F		Central consol F	
Windows electric R		Luggage cover	
Cruise Control		Front parking sensors	
Steering wheel multifunctional		Rear parking sensors	
Radio multimedia		Type of Tow bar	Tow bar removable
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/55/16/91 V LightMetal			
Summer tyres:	Fr.L.	Uniroyal: 4 mm	Fr.R.	Uniroyal: 4 mm
	Re.L.	Uniroyal: 4 mm	Re.R.	Uniroyal: 4 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	500,50
Bumper R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Sill outer R, Dent(s), LI - Repair and paint (complete)	310,50



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Bumper F, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Alloy rim R L, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Alloy rim F L, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Alloy rim R R, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Door R R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display