



**VOLKSWAGEN GOLF SPORTSVAN: 1LCF263**

Vinnnummer:	<b>WVWZZZAUZFW616330</b>	Versionname:	
First Registrationdate:	<b>18/08/2015</b>	Fiscalpower:	
Expertise Mileage:	<b>269747</b>	Power Kw:	<b>81</b>
Bodytype:		Body color:	<b>Grey</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>2624</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Windows electric F	Central consol F
Windows electric R	Luggage cover
Cruise Control	Front parking sensors
Steering wheel multifunctional	Rear parking sensors
Radio multimedia	Type of Tow bar
Type of headlighting	<b>Headlighting Halogen</b>
Type of GPS	<b>GPS big screen color</b>
Type of Lining	<b>Lining fabrics</b>
Type of climate control	<b>Autom climate control</b>
	<b>No Tow bar</b>

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>NOT OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>195/65/15/91 V Steel</b>			
Summer tyres:	Fr.L.	<b>Michelin: 3 mm</b>	Fr.R.	<b>Michelin: 3 mm</b>
	Re.L.	<b>Michelin: 4 mm</b>	Re.R.	<b>Michelin: 4 mm</b>

**Assistance equipment**

Spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
Number of charging cables (normal)	<b>0</b>		
Number of charging cables (rapid charge)	<b>0</b>		

Total cost ex VAT	1691,61
Door R R, Scratch(es), LI - Repair and paint (complete)	318,35



Sill outer L, Dent(s), LI - Repair and paint (complete)

310,50



Sill outer R, Dent(s), LI - Repair and paint (complete)

310,50



Bumper F, Scratch(es), Acceptable

0,00

*No pictures to display*

Door F L, Scratch(es), LI - Repair and paint (complete)

318,35



Bumper R, Dent(s) and scratch(es), It - Spot repair

115,56



Tailgate, Scratch(es), Acceptable

0,00

*No pictures to display*

Engine, Not functioning (well), Acceptable

0,00

*No pictures to display*

Door R L, Scratch(es), LI - Repair and paint (complete)

318,35



Wheel cover F R, Scratch(es), Acceptable

0,00

*No pictures to display*

Rear window, Scratch(es), Acceptable

0,00

*No pictures to display*