


BMW X4: 1HSG310

Vinnumber:	WBAXX110500L84806	Versionname:	X4 xDrive20dA 163PK Aut.
First Registrationdate:	19/09/2014	Fiscalpower:	
Expertise Mileage:	95677	Power Kw:	120
Bodytype:		Body color	Dark Grey
Gearbox:	Automatic	Paint type	Metalic
Transmission:	4 Wheel	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	3125
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD		Central consol F	
GPS storage	HD	Luggage cover	
GPS storage		Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	Tow bar fixed
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting Xenon		
Type of GPS	GPS big screen color		
Type of Lining	Lining artificial leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

Summer tyres:	245/50/18/100 W LightMetal			
	Fr.L.	Pirelli: 4 mm	Fr.R.	Pirelli: 4 mm
	Re.L.	Pirelli: 5 mm	Re.R.	Pirelli: 5 mm

Assistance equipment

Number of charging cables (normal)	0
Number of charging cables (rapid charge)	0

Total cost ex VAT	2436,91
Door F R, Dent(s) and scratch(es), LI - Repair and paint (complete)	382,02



Bumper Trim F, Deformed / Strained, Forfeit

24,00




Rocker panel inner R R, Scratch(es), Acceptable

0,00

No pictures to display

Tailgate, Dent(s) and scratch(es), LI - Repair and paint (complete)

362,02



Door F L, Dent(s), PDR - Paintless dent repair

82,80



Roof, Chemical pollution, LI - Repair and paint (complete)

601,80



Seat cover F L, Worn, Acceptable

0,00



Bumper R, Scratch(es), LI - Repair and paint (complete)

254,16




Wing R R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Alloy rim F R polished, Scratch(es), Acceptable	0,00
---	------

No pictures to display

Door R L, Dent(s) and scratch(es), LI - Repair and paint (complete)	382,02
---	--------



Bonnet, Chemical polution, LI - Repair and paint (complete)	348,09
---	--------

