



CITROEN BERLINGO: EX5295

Vinnumber:	VF77B9HF0GJ702071	Versionname:	1.6 HDI 90 SHORT FRESH NEW
First Registrationdate:	4/07/2016	Fiscalpower:	
Expertise Mileage:	36327	Power Kw:	66
Bodytype:	Transporter	Body color:	White
Gearbox:	MAN 5 VIT	Paint type:	Opaque
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3206
Number of doors:	5		
Number of seats:	3		
Number head rests:	3		
Rims summer:	Steel		
Category:	Light Commercial Vehicle		
Oil level:	OK		

Options

Radio CD		Type of Tow bar	No Tow bar
Windows electric F			
Cruise Control			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	No GPS		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	195/65/15/91 T Steel			
Winter tyres:	Fr.L.	Kleber: 4 mm	Fr.R.	Kleber: 4 mm
	Re.L.	Kleber: 5 mm	Re.R.	Kleber: 5 mm

Assistance equipment

Spare wheel	Yes
Number of charging cables (normal)	0
Number of charging cables (rapid charge)	0

Total cost ex VAT	1571,10
Door F R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Trunk door R R, Dent(s) and scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Wing F L, Dent(s) and scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Boot carpet, Tear, E - Replace	75,00



Roof, Dent(s), LI - Repair and paint (complete)

409,13



Bonnet prop, Missing, E - Replace

20,00



Wing R L, Dent(s) and scratch(es), LI - Repair and paint (complete)

231,15



Rearlight R , Broken, E - Replace

91,50



Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete)

238,76



Bumper F, Scratch(es), Acceptable 0,00

No pictures to display

Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 231,15



Bumper R, Scratch(es), LI - Repair and paint (complete) 158,85



Trunk door R L, Dent(s) and scratch(es), It - Spot repair 115,56



Door F L, Scratch(es), Acceptable 0,00

No pictures to display