



VOLVO V40 CROSS COUNTRY: 1JXZ854

Vinnumber:	YV1MZ8451F2075215	Versionname:	1.6 D2 KINETIC
First Registrationdate:	17/03/2015	Fiscalpower:	
Expertise Mileage:	146060	Power Kw:	84
Bodytype:	Hatchback	Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metallic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OVER 3811 KM	Parking lot:	4111
Maintenance:	OK		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Windows electric F	Central consol F
Windows electric R	Luggage cover
Cruise Control	Rear parking sensors
Steering wheel multifunctional	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/55/16/92 W LightMetal			
Summer tyres:	Fr.L.	Bridgestone: 1 mm	Fr.R.	Bridgestone: 1 mm
	Re.L.	Bridgestone: 5 mm	Re.R.	Bridgestone: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	2766,76
Bumper trim R, Broken, E - Replace	114,60



Mirror side blinker R, Broken, Forfeit

74,62



Wing R L, Dent(s), PDR - Paintless dent repair

63,00



Door panel R L, Scratch(es), Smart repair

110,64



Spoiler R, Scratch(es), Paint

100,00



Ceiling, Stain, Cleaning

25,00



Bumper F, Scratch(es), It - Spot repair

115,56



Wing F L, Dent(s) and scratch(es), LI - Repair and paint (partial)

220,18



Alloy rim F L, Scratch(es), LI - Repair and paint (complete)

95,00





Bonnet, Chemical polution, 67 - Polish

50,00



Sill outer R, Scratch(es), E - Replace

111,25



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00



Tyre F R, Worn, E - Replace

132,00



Windscreen, Scratch(es), E - Replace

487,20



Door R R, Scratch(es), LI - Repair and paint (complete)

318,35



Bumper R, Scratch(es), LI - Repair and paint (complete)

211,80



Wing R R, Scratch(es), It - Spot repair 115,56



Seat cover R, Stain, Cleaning 50,00



Tyre F L, Worn, E - Replace 132,00



Door F R, Scratch(es), 67 - Polish 50,00



Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00

