


RENAULT Kangoo Express: 1FCL711

Vinnumber:	VF1FW15B548774031	Versionname:	KANGOO Expr. B/F PLC Gr.Conf.(EU5)90PK
First Registrationdate:	24/05/2013	Fiscalpower:	
Expertise Mileage:	107611	Power Kw:	66
Bodytype:		Body color:	White
Gearbox:	MAN 5 VIT	Paint type:	Opaque
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2614
Number of doors:	5		
Number of seats:	2		
Number head rests:	2		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD		Central consol F	
Windows electric F		Type of Tow bar	No Tow bar
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	No GPS		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

195/65/15/91 T Steel				
Summer tyres:	Fr.L.	Continental: 5 mm	Fr.R.	Continental: 5 mm
	Re.L.	Continental: 5 mm	Re.R.	Continental: 5 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	269,64
Bodywork, Not original part, Acceptable	0,00
<i>No pictures to display</i>	
Rearview mirror housing L, Crack, E - Replace	74,00



Wing R R, Scratch(es), Acceptable 0,00

No pictures to display

Sliding door R, Scratch(es), Acceptable 0,00

No pictures to display

Wheel hub cap F L, Missing, E - Replace 10,00



Door F L, Dent(s) and scratch(es), Acceptable 0,00

No pictures to display

Boot carpet, Damaged, E - Replace 75,00



Bonnet, Dent(s) and scratch(es), Acceptable 0,00

No pictures to display

Bumper R, Scratch(es), Acceptable 0,00

No pictures to display

Bumper F, Scratch(es), Smart repair 110,64

