


BMW 1: 1HKL126

Vinnumber:	WBA1C11050P529500	Versionname:	1 BER HATCH 118d 136PK
First Registrationdate:	11/08/2014	Fiscalpower:	
Expertise Mileage:	149566	Power Kw:	100
Bodytype:		Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3819
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

GPS storage		Sun Roof electric	
GPS storage	HD	Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Rear parking sensors	
Steering wheel multifunctional		Type of Tow bar	No Tow bar
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/55/16/91 V LightMetal			
Summer tyres:	Fr.L.	Michelin: 7 mm	Fr.R.	Michelin: 7 mm
	Re.L.	Michelin: 6 mm	Re.R.	Michelin: 6 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	2100,47
Tailgate, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Alloy rim F L, Scratch(es), LI - Repair and paint (complete)	95,00



Headlight L, Broken, E - Replace 396,00



Door R L, Dent(s), PDR - Paintless dent repair 63,00



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Outer backrest protection L, Scratch(es), E - Replace 92,98



Bumper trim R, Missing, E - Replace 46,25



Boot cover, Scratch(es), E - Replace 50,00





Outer backrest protection R, Scratch(es), E - Replace

107,38



Door R R, Scratch(es), Acceptable

0,00

No pictures to display

Door F L, Dent(s), PDR - Paintless dent repair

63,00



Bumper F, Dent(s) and scratch(es), LI - Repair and paint (complete)

211,80



Wing R R, Scratch(es), Acceptable

0,00

No pictures to display

Door F R, Dent(s), PDR - Paintless dent repair

63,00



Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete)

211,80





Bonnet, Chemical pollution, LI - Repair and paint (complete)

290,08



Alloy rim R L, Scratch(es), LI - Repair and paint (complete)

95,00



Wing F L, Dent(s), LI - Repair and paint (complete)

220,18

