



AUDI A3 BERLINE: 1LLA109

Vinnumber:	WAUZZZ8V4G1033134	Versionname:	1.6 TDI ULTRA 81KW ATTRACTION
First Registrationdate:	16/10/2015	Fiscalpower:	
Expertise Mileage:	87783	Power Kw:	81
Bodytype:		Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	3812
Maintenance:	5500		
Maintenance:	198 DAGEN		
Battery functioning:	Yes		
Number of doors:	4		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
GPS storage	Rear parking sensors
GPS storage	SD Type of Tow bar
Windows electric F	Tow bar removable
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Seats F heated	
Radio multimedia	
Type of headlighting	Headlighting Xenon
Type of GPS	GPS big screen color
Type of Lining	Lining leather
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/55/16/91 V LightMetal				
Summer tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	231,12
-------------------	---------------

Door R R, Scratch(es), Acceptable	0,00
-----------------------------------	-------------

Wing R R, Dent(s) and scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Rear bulkhead lining, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Seat F L compl, Worn, Acceptable	0,00
<i>No pictures to display</i>	
Door R L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Alloy rim F R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Bumper R, Dent(s) and scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Sill trim L, Scratch(es), It - Spot repair	115,56



Steering wheel, Worn, Acceptable	0,00
<i>No pictures to display</i>	
Outer door handle F R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Door F R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Bumper F, Scratch(es), It - Spot repair	115,56



Door F L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Rear window, Not original part, Acceptable	0,00
<i>No pictures to display</i>	