



**AUDI A4 AVANT: 1KUC040**

|                                    |                          |              |                                  |
|------------------------------------|--------------------------|--------------|----------------------------------|
| Vinnumber:                         | <b>WAUZZZ8K8FA150462</b> | Versionname: | <b>2.0 TDI 100KW MULTITRONIC</b> |
| First Registrationdate:            | <b>3/07/2015</b>         | Fiscalpower: |                                  |
| Expertise Mileage:                 | <b>112389</b>            | Power Kw:    | <b>100</b>                       |
| Bodytype:                          |                          | Body color:  | <b>Blue</b>                      |
| Gearbox:                           | <b>Automatic</b>         | Paint type:  | <b>Metalic</b>                   |
| Transmission:                      | <b>Front</b>             | Rims summer: | <b>Aluminium</b>                 |
| Fueltype:                          | <b>Diesel</b>            | Oil level:   | <b>OK</b>                        |
| Battery functioning:               | <b>Yes</b>               | Parking lot: | <b>1714</b>                      |
| Number of doors:                   | <b>5</b>                 |              |                                  |
| Number of seats:                   | <b>5</b>                 |              |                                  |
| Number head rests:                 | <b>5</b>                 |              |                                  |
| Rims summer:                       | <b>Aluminium</b>         |              |                                  |
| Category:                          | <b>Passenger Car</b>     |              |                                  |
| Oil level:                         | <b>OK</b>                |              |                                  |
| Registration Certificate Car (BE): | <b>Yes</b>               |              |                                  |

**Options**

|                                |                              |                      |                   |
|--------------------------------|------------------------------|----------------------|-------------------|
| Radio CD                       |                              | Sun Roof electric    |                   |
| GPS storage                    |                              | Panoramic roof       |                   |
| GPS storage                    | <b>HD</b>                    | Central consol F     |                   |
| Windows electric F             |                              | Luggage cover        |                   |
| Windows electric R             |                              | Rear parking sensors |                   |
| Cruise Control                 |                              | Type of Tow bar      | <b>No Tow bar</b> |
| Steering wheel multifunctional |                              |                      |                   |
| Seats F heated                 |                              |                      |                   |
| Radio multimedia               |                              |                      |                   |
| Type of headlighting           | <b>Headlighting Xenon</b>    |                      |                   |
| Type of GPS                    | <b>GPS big screen color</b>  |                      |                   |
| Type of Lining                 | <b>Lining leather</b>        |                      |                   |
| Type of climate control        | <b>Autom climate control</b> |                      |                   |

**Limited Technical Inspection**

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                     |           | Lighting            | <b>OK</b>  |
|                     |           | Wiperblades         | <b>OK</b>  |

**Degree of wear**

|                                  |       |                       |       |                       |
|----------------------------------|-------|-----------------------|-------|-----------------------|
| <b>205/60/16/92 V LightMetal</b> |       |                       |       |                       |
| Summer tyres:                    | Fr.L. | <b>Michelin: 3 mm</b> | Fr.R. | <b>Michelin: 3 mm</b> |
|                                  | Re.L. | <b>Michelin: 4 mm</b> | Re.R. | <b>Michelin: 4 mm</b> |

**Assistance equipment**

|  |            |
|--|------------|
| Emergency spare wheel                    | <b>Yes</b> |
| Number of charging cables (normal)       | <b>0</b>   |
| Number of charging cables (rapid charge) | <b>0</b>   |

|                          |               |
|--------------------------|---------------|
| <b>Total cost ex VAT</b> | <b>501,88</b> |
|--------------------------|---------------|


|                                      |             |
|--------------------------------------|-------------|
| <b>Wing R R, Dent(s), Acceptable</b> | <b>0,00</b> |
|--------------------------------------|-------------|

*No pictures to display*

|  |             |
|--|-------------|
| <b>Bumper F, Scratch(es), Acceptable</b> | <b>0,00</b> |
|--|-------------|

No pictures to display

Bonnet, Dent(s) and scratch(es), LI - Repair and paint (complete) 290,08



Door R R, Scratch(es), Acceptable 0,00

No pictures to display

Wing F L, Scratch(es), Acceptable 0,00

No pictures to display

Rear window, Scratch(es), E - Replace 0,00



Door F R, Scratch(es), Acceptable 0,00

No pictures to display

Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80





|  |      |
|--|------|
| Rearview mirror housing R, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i>                      |      |
| Roof, Chemical polution, 67 - Polish               | 0,00 |
| <i>No pictures to display</i>                      |      |
| Wing R L, Scratch(es), Acceptable                  | 0,00 |
| <i>No pictures to display</i>                      |      |
| Door F L, Scratch(es), Acceptable                  | 0,00 |
| <i>No pictures to display</i>                      |      |
| Rear spoiler, Dent(s), Acceptable                  | 0,00 |
| <i>No pictures to display</i>                      |      |