



**AUDI Q3: 1LJK483**

Vinnumber:	<b>WAUZZZ8U3GR040245</b>	Versionname:	<b>1.4 TFSI COD 110KW</b>
First Registrationdate:	<b>5/10/2015</b>	Fiscalpower:	
Expertise Mileage:	<b>43637</b>	Power Kw:	<b>110</b>
Bodytype:	<b>SUV</b>	Body color:	<b>Black</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metallic</b>
Transmission:		Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Petrol</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>4731</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD	Sun Roof electric
Windows electric F	Panoramic roof
Windows electric R	Central consol F
Cruise Control	Luggage cover
Steering wheel multifunctional	Front parking sensors
Seats F heated	Rear parking sensors
Radio multimedia	Type of Tow bar
Type of headlighting	<b>Headlighting LED</b>
Type of GPS	<b>GPS big screen color</b>
Type of Lining	<b>Lining leather</b>
Type of climate control	<b>Autom climate control</b>
Sport seats	<b>No Tow bar</b>

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>


**Degree of wear**

<b>235/55/17/99 V LightMetal</b>				
Summer tyres:	Fr.L.	<b>Continental: 5 mm</b>	Fr.R.	<b>Continental: 5 mm</b>
	Re.L.	<b>Continental: 7 mm</b>	Re.R.	<b>Continental: 7 mm</b>

**Assistance equipment**

Emergency spare wheel	<b>Yes</b>
-----------------------	------------

Total cost ex VAT	<b>618,36</b>
Bumper R, Scratch(es), LI - Repair and paint (complete)	<b>211,80</b>



Door F L, Dent(s), PDR - Paintless dent repair	63,00
--	-------



Bonnet, Chemical polution, 67 - Polish	0,00
--	------

No pictures to display

Door moulding Lower F R, Scratch(es), E - Replace	114,00
---	--------



Door R L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Rearview mirror housing R, Scratch(es), LI - Repair and paint (complete)	115,56
--	--------



Door moulding Lower R R, Scratch(es), E - Replace	114,00
---	--------

