


BMW 3: 1HJH312

Vinnumber:	WBA3Y31070D644946	Versionname:	3 GRAN TURISMO 320d 163PK
First Registrationdate:	1/08/2014	Fiscalpower:	
Expertise Mileage:	114755	Power Kw:	120
Bodytype:		Body color:	Brown
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	2304
Maintenance:	OVER 20000 KM		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

GPS storage	HD	Sun Roof electric	
GPS storage		Panoramic roof	
Windows electric F		Central consol F	
Windows electric R		Luggage cover	
Cruise Control		Front parking sensors	
Steering wheel multifunctional		Rear parking sensors	
Radio multimedia		Type of Tow bar	No Tow bar
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

225/55/17/97 W LightMetal				
Summer tyres:	Fr.L.	Continental: 7 mm	Fr.R.	Continental: 7 mm
	Re.L.	Continental: 4 mm	Re.R.	Continental: 4 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	2079,71
Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete)	366,35



Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



Alloy rim R L, Scratch(es), LI - Repair and paint (complete) 95,00



Window F L door, Scratch(es), E - Replace 187,23



Bumper F, Scratch(es), LI - Repair and paint (complete) 211,80



Internal Boot Lining L, Dirty, Chemical cleaning 25,00



Wing R L, Scratch(es), LI - Repair and paint (complete) 308,20



Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete) 307,80



Sill outer R, Scratch(es), LI - Repair and paint (complete)

310,50



Window R L door, Scratch(es), E - Replace

172,83

