

**BMW 3: 1GNZ191**

| | | | |
|------------------------------------|--------------------------|--------------|----------------------------------|
| Vinnumber: | WBA3Y11020D449308 | Versionname: | 3 GRAN TURISMO 318d 136PK |
| First Registrationdate: | 21/03/2014 | Fiscalpower: | |
| Expertise Mileage: | 99327 | Power Kw: | 100 |
| Bodytype: | | Body color: | Brown |
| Gearbox: | MAN 6 VIT | Paint type: | Metalic |
| Transmission: | Back | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | 2125 |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

Options

| | | | |
|--------------------------------|----------------------------------|-----------------------|-------------------|
| Radio CD | | Sun Roof electric | |
| Windows electric F | | Panoramic roof | |
| Windows electric R | | Central consol F | |
| Cruise Control | | Luggage cover | |
| Steering wheel multifunctional | | Front parking sensors | |
| Seats F heated | | Rear parking sensors | |
| Radio multimedia | | Type of Tow bar | No Tow bar |
| Type of headlighting | Headlighting Xenon | | |
| Type of GPS | GPS big screen color | | |
| Type of Lining | Lining artificial leather | | |
| Type of climate control | Autom climate control | | |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|---------------|----------------------------------|-----------------------|-------|-----------------------|
| | 225/55/17/97 W LightMetal | | | |
| Summer tyres: | Fr.L. | Michelin: 4 mm | Fr.R. | Michelin: 4 mm |
| | Re.L. | Michelin: 4 mm | Re.R. | Michelin: 4 mm |

Assistance equipment

| | | | |
|--|------------|------------|------------|
| Repair kit | Yes | Compressor | Yes |
| Number of charging cables (normal) | 0 | | |
| Number of charging cables (rapid charge) | 0 | | |

| | |
|--------------------------|---------------|
| Total cost ex VAT | 211,80 |
|--------------------------|---------------|

| | |
|--|-------------|
| Bonnet, Stone chip(s), Acceptable | 0,00 |
|--|-------------|

No pictures to display

| | |
|--|-------------|
| Rear spoiler, Dent(s), Acceptable | 0,00 |
|--|-------------|

No pictures to display

| | |
|--|---------------|
| Bumper F, Dent(s) and scratch(es), LI - Repair and paint (complete) | 211,80 |
|--|---------------|

