



BMW i3: 1SRV730

| | | | |
|------------------------------------|--------------------------|--------------|--------------------|
| Vinnumber: | WBY1Z610407A09093 | Versionname: | i3 Advanced |
| First Registrationdate: | 29/06/2017 | Fiscalpower: | |
| Expertise Mileage: | 31112 | Power Kw: | 125 |
| Bodytype: | | Body color: | Grey |
| Gearbox: | Automatic | Paint type: | Metalic |
| Transmission: | | Rims summer: | Aluminium |
| Fueltype: | Electric | Oil level: | OK |
| Maintenance: | OK | Parking lot: | 2633 |
| Battery functioning: | Yes | | |
| Number of doors: | 4 | | |
| Number of seats: | 4 | | |
| Number head rests: | 4 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

Options

| | |
|--------------------------------|------------------------------|
| Windows electric F | Central consol F |
| Cruise Control | Luggage cover |
| Steering wheel multifunctional | Rear parking sensors |
| Radio multimedia | |
| Type of headlighting | Headlighting Halogen |
| Type of GPS | GPS big screen color |
| Type of Lining | Lining fabrics |
| Type of climate control | Autom climate control |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|---------------|-----------------------------------|--------------------------|-------|--------------------------|
| Winter tyres: | 155/70/19/92 MS LightMetal | | | |
| | Fr.L. | Continental: 5 mm | Fr.R. | Continental: 5 mm |
| | Re.L. | Continental: 6 mm | Re.R. | Continental: 6 mm |
| | | | | |

Assistance equipment

| | | | |
|------------------------------------------|------------|------------|------------|
| Repair kit | Yes | Compressor | Yes |
| Number of charging cables (normal) | 1 | | |
| Number of charging cables (rapid charge) | 1 | | |

| | |
|-------------------|---------------|
| Total cost ex VAT | 349,16 |
|-------------------|---------------|

| | |
|--------------------------------------------------------------|--------------|
| Alloy rim F R, Scratch(es), LI - Repair and paint (complete) | 95,00 |
|--------------------------------------------------------------|--------------|



Bumper R, Scratch(es), LI - Repair and paint (complete)

254,16

