



<b>BMW 3: 1HUJ483</b>			
Vinnumber:	<b>WBA3L11080K177065</b>	Versionname:	<b>3 TOURING 320d Eff.Dyn.Ed. 163PK</b>
First Registrationdate:	<b>6/10/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>185234</b>	Power Kw:	<b>120</b>
Bodytype:		Body color:	<b>Dark Grey</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Back</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance	<b>06-2021 OU 17.000 KM</b>	Parking lot:	<b>3112</b>
Maintenance	<b>OK</b>		
Battery functioning	<b>Yes</b>		
Number of doors	<b>5</b>		
Number of seats	<b>5</b>		
Number head rests	<b>5</b>		
Rims summer	<b>Aluminium</b>		
Category	<b>Passenger Car</b>		
Oil level	<b>OK</b>		
Registration Certificate Car (BE)	<b>Yes</b>		

<b>Options</b>			
Radio CD		Central consol F	
GPS storage	<b>HD</b>	Luggage cover	
GPS storage		Rear parking sensors	
Windows electric F		Type of Tow bar	<b>No Tow bar</b>
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining artificial leather</b>		
Type of climate control	<b>Manual climate control</b>		

<b>Limited Technical Inspection</b>			
Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

<b>Degree of wear</b>			
Summer tyres:	<b>205/60/16/92 W LightMetal</b>		
	Fr.L.	Fr.R.	Michelin: 5 mm
	Re.L.	Re.R.	Michelin: 5 mm

<b>Assistance equipment</b>			
Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
Total cost ex VAT			<b>423,60</b>
Tailgate, Scratch(es), Acceptable			<b>0,00</b>
<i>No pictures to display</i>			
Bonnet, Dent(s) and scratch(es), Acceptable			<b>0,00</b>
<i>No pictures to display</i>			
Bumper F, Scratch(es), LI - Repair and paint (complete)			<b>211,80</b>



Bumper R, Scratch(es), LI - Repair and paint (complete)

211,80

