



OPEL Insignia: 1HUP162

Vinnumber:	WOLGT8E54E1172093	Versionname:	INSIGNIA BRE ecoFLEX Cosmo 140PK
First Registrationdate:	7/10/2014	Fiscalpower:	
Expertise Mileage:	97489	Power Kw:	103
Bodytype:	Break	Body color:	Dark Brown
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3724
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Windows electric F	Seats electric F L	
Windows electric R	Central consol F	
Cruise Control	Luggage cover	
Steering wheel multifunctional	Front parking sensors	
Seats F heated	Rear parking sensors	
Radio multimedia	Type of Tow bar	No Tow bar
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining leather	
Type of climate control	Autom climate control	
Sport seats		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear


225/55/17/101 Y LightMetal				
Summer tyres:	Fr.L.	Uniroyal: 6 mm	Fr.R.	Uniroyal: 6 mm
	Re.L.	Michelin: 6 mm	Re.R.	Michelin: 6 mm

Assistance equipment


Spare wheel	Yes	Jack	Yes
Total cost ex VAT			2168,18
Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete)			0,00



Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



Tailgate, Scratch(es), LI - Repair and paint (complete) 301,68



Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00



Rearview mirror housing R, Scratch(es), LI - Repair and paint (complete) 115,56



Door F L, Dent(s) and scratch(es), LI - Repair and paint (complete) 318,35




Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete) 211,80





Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete)

318,35



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00



Rearview mirror housing L, Scratch(es), LI - Repair and paint (complete)

115,56



Wing R L, Scratch(es), Acceptable

0,00

No pictures to display

Bumper F, Dent(s) and scratch(es), LI - Repair and paint (complete)

211,80



Bonnet, Dent(s) and scratch(es), LI - Repair and paint (complete)

290,08

