



OPEL CORSA: 1LHJ295

Vinnumber:	W0L0XEP68G4017629	Versionname:	1.4 66KW LPG ECOFLEX ENJOY
First Registrationdate:	29/09/2015	Fiscalpower:	
Expertise Mileage:	105859	Power Kw:	66
Bodytype:		Body color:	Silver
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Gas	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3625
Number of doors:	5		
Number of seats:	5		
Number head rests:	4		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Luggage cover	
GPS storage	HD	Type of Tow bar	No Tow bar
GPS storage			
Windows electric F			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

185/65/15/88 H Steel				
Summer tyres:	Fr.L.	Continental: 4 mm	Fr.R.	Continental: 4 mm
	Re.L.	Continental: 5 mm	Re.R.	Continental: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------


Total cost ex VAT	541,38
-------------------	---------------

Sill outer L, Dent(s), Acceptable	0,00
-----------------------------------	-------------

No pictures to display

Bonnet, Dent(s), LI - Repair and paint (complete)	424,06
---------------------------------------------------	---------------





Bumper F, Scratch(es), Acceptable 0,00

No pictures to display

Wheel cover R R, Scratch(es), E - Replace 24,00



Instrument panel cover, Not functioning (well), P - Check 0,00



Bumper grille, Broken, E - Replace 30,72



Wheel cover F L, Scratch(es), E - Replace 24,00



Rearview mirror housing R, Scratch(es), Acceptable 0,00

No pictures to display

Handbrake cover, Broken, E - Replace 14,60



Wheel cover F R, Scratch(es), E - Replace 24,00

