



RENAULT TRAFIC: 1RSJ162

Vinnumber:	VF1FL000456628471	Versionname:	L2H1 1.6 dCi 125 Energy Grand C. DC 2.9T
First Registrationdate:	17/02/2017	Fiscalpower:	
Expertise Mileage:	108879	Power Kw:	92
Bodytype:	Transporter	Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	LCV13
Number of doors:	5		
Number of seats:	6		
Number head rests:	6		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

GPS storage	HD	Central consol F	
GPS storage		Rear parking sensors	
Windows electric F		Type of Tow bar	Tow bar fixed
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/65/16/105 T Steel				
Winter tyres:	Fr.L.	Goodyear: 6 mm	Fr.R.	Goodyear: 6 mm
	Re.L.	Goodyear: 8 mm	Re.R.	Goodyear: 8 mm

Assistance equipment

Spare wheel	Yes
Number of charging cables (normal)	0
Number of charging cables (rapid charge)	0

Total cost ex VAT	3346,44
Rear wiper arm, Missing, E - Replace	40,00



Trunk door R R, Dent(s) and scratch(es), It - Spot repair

115,56



Door R R, Scratch(es), Acceptable

0,00

No pictures to display

Door F R, Dent(s) and scratch(es), LI - Repair and paint (complete)

238,76



Roof, Chemical polution, LI - Repair and paint (complete)

409,13



Wheel cover F R, Scratch(es), Acceptable

0,00

No pictures to display

Bumper F, Broken, Le - Replace and paint

0,00






Ignition key, Missing, E - Replace 150,00

No pictures to display

Wing R L, Dent(s) and scratch(es), LI - Repair and paint (complete) 231,15




Wing F L, Scratch(es), Acceptable 0,00

No pictures to display

Wing trim R R, Scratch(es), Le - Replace and paint 75,00



Bumper corner R R, Scratch(es), It - Spot repair 115,56



Roof pillar R, Scratch(es), Acceptable 0,00

No pictures to display

Floor covering F L, Hole, Smart repair 64,32





Wheel cover R R, Broken, E - Replace

22,50



Rearlight L, Broken, E - Replace

91,50



Roof pillar L, Dent(s) and scratch(es), LI - Repair and paint (complete)

237,14



Bonnet, Chemical polution, LI - Repair and paint (complete)

217,56



Seat cover F L, Hole, E - Replace

300,00




Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete)

158,85



Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete)

423,15



Interior, Dirty, Cleaning 100,00



Trunk door R L, Scratch(es), Acceptable 0,00

No pictures to display 22,50

Wheel cover F L, Scratch(es), E - Replace 22,50



Door F L, Dent(s) and scratch(es), LI - Repair and paint (complete) 238,76



Cupholder F, Broken, E - Replace 20,00



Wing trim R L, Scratch(es), Le - Replace and paint

75,00

