



OPEL Zafira: 1HAN259

Vinnumber:	WOLPE9E31E2084766	Versionname:	ZAFIRA TOURER ecoFL.Cosmo S/S 136PK
First Registrationdate:	4/06/2014	Fiscalpower:	
Expertise Mileage:	144264	Power Kw:	100
Bodytype:	SUV	Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2810
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F	
Windows electric F	Luggage cover	
Windows electric R	Front parking sensors	
Cruise Control	Rear parking sensors	
Steering wheel multifunctional	Type of Tow bar	Tow bar removable
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining semi-leather	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

215/60/16/99 H LightMetal				
Summer tyres:	Fr.L.	Michelin: 2 mm	Fr.R.	Michelin: 2 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm


Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT 1102,40

Windscreen, Stone chip(s), Acceptable 0,00





Inner seat cover L, Broken, Smart repair

110,64



Door R L, Scratch(es), Acceptable

0,00

No pictures to display

Wing R R, Scratch(es), Acceptable

0,00

No pictures to display

Wing F L, Scratch(es), 67 - Polish

0,00

No pictures to display

Roof pillar R, Chemical polution, LI - Repair and paint (complete)

220,18



Roof, Chemical polution, LI - Repair and paint (complete)

481,50



Door F L, Scratch(es), Acceptable

0,00

No pictures to display