



RENAULT KANGOO EXPRESS: 1 SDU435

Vinnumber:	VF1FW50J156670810	Versionname:	Energy dCi 75 Grand Confort
First Registrationdate:	19/04/2017	Fiscalpower:	
Expertise Mileage:	87386	Power Kw:	55
Bodytype:		Body color:	White
Gearbox:	MAN 5 VIT	Paint type:	Opaque
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3631
Number of doors:	5		
Number of seats:	2		
Number head rests:	2		
Rims summer:	Steel		
Category:	Light Commercial Vehicle		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Windows electric F		Type of Tow bar	Tow bar fixed
Windows electric R			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	No GPS		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	195/65/15/91 T Steel			
Winter tyres:	Fr.L.	Continental: 4 mm	Fr.R.	Continental: 4 mm
	Re.L.	Continental: 4 mm	Re.R.	Continental: 4 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT 765,20

Reflector, Broken, E - Replace 54,00



Windscreen, Crack, E - Replace 0,00



Sidewall RL (LCV), Dent(s), Acceptable 0,00

No pictures to display

Wing trim R R, Deformed / Strained, E - Replace 69,00



Sliding door R, Dent(s), Acceptable 0,00

No pictures to display

Bumper R, Deformed / Strained, Smart repair 110,64



Wheel cover F L, Deformed / Strained, Acceptable 0,00

No pictures to display

Bumper F, Scratch(es), Acceptable 0,00

No pictures to display

Interior, Dirty, Cleaning 50,00



Bonnet, Dent(s), LI - Repair and paint (complete) 217,56



Wheel cover F R, Scratch(es), E - Replace 22,50



Rearlight R, Broken, E - Replace 91,50



Rearview mirror housing R, Scratch(es), Acceptable 0,00

No pictures to display

Ignition key, Missing, E - Replace 150,00

No pictures to display