


RENAULT Clio: 1GGT165

Vinnumber:	VF15RJL0H50197943	Versionname:	CLIO IV BER e-Business St&St 90PK
First Registrationdate:	4/02/2014	Fiscalpower:	
Expertise Mileage:	190723	Power Kw:	66
Bodytype:		Body color:	Silver
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3205
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

GPS storage		Central consol F	
GPS storage	HD	Luggage cover	
Windows electric F		Rear parking sensors	
Cruise Control		Type of Tow bar	No Tow bar
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK


Degree of wear

	185/65/15/88 T Steel			
Summer tyres:	Fr.L.	Dunlop: 2 mm	Fr.R.	Dunlop: 2 mm
	Re.L.	Bridgestone: 5 mm	Re.R.	Bridgestone: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	1576,20
Bumper R, Scratch(es), LI - Repair and paint (complete)	169,44



Armrest F Mid, Worn, Acceptable

0,00



Tailgate, Scratch(es), Acceptable

0,00

No pictures to display

Bonnet, Dent(s), Acceptable

0,00

No pictures to display

Wheel cover R L, Scratch(es), E - Replace

24,00



Door F L, Bad repair, Acceptable

0,00



Windscreen, Scratch(es), Acceptable

0,00



Protection plate M, Deformed / Strained, E - Replace

74,00



Door F R, Scratch(es), Acceptable

0,00

No pictures to display

Ignition key, Broken, E - Replace

150,00



Door R R, Scratch(es), LI - Repair and paint (complete)

254,68



Wheel cover R R, Scratch(es), E - Replace

24,00



Floor covering F L, Hole, E - Replace

240,00



Door R L, Scratch(es), Acceptable

0,00

No pictures to display

Seat cover F L, Hole, E - Replace

312,00



Wing R R, Scratch(es), Acceptable

0,00

No pictures to display


Boot cover, Scratch(es), Acceptable

0,00



Bumper F, Dent(s) and scratch(es), LI - Repair and paint (complete)

169,44





Wheel cover F R, Scratch(es), E - Replace 24,00



Roof, Dent(s), Acceptable 0,00

No pictures to display

Door panel R R, Scratch(es), Smart repair 110,64



Wheel cover F L, Scratch(es), E - Replace 24,00

