



VOLKSWAGEN GOLF VARIANT: 1JJG765

Vinnumber:	WVWZZZAUZFP579192	Versionname:	1.6 CR TDI 77KW BMT TRENDLINE
First Registrationdate:	2/01/2015	Fiscalpower:	
Expertise Mileage:	141336	Power Kw:	77
Bodytype:		Body color:	Beige
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4611
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Windows electric F	Central consol F
Windows electric R	Luggage cover
Cruise Control	Front parking sensors
Steering wheel multifunctional	Rear parking sensors
Radio multimedia	Type of Tow bar
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control
	Tow bar fixed

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

195/65/15/91 H Steel				
Summer tyres:	Fr.L.	Dunlop: 4 mm	Fr.R.	Dunlop: 4 mm
	Re.L.	Dunlop: 4 mm	Re.R.	Dunlop: 4 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	1152,88
--------------------------	----------------

Wheel cover R L, Scratch(es), Acceptable	0,00
---	-------------

No pictures to display

Sill outer R, Dent(s), Acceptable	0,00
--	-------------

No pictures to display

Rear window, Scratch(es), Acceptable	0,00
---	-------------


No pictures to display

Wiper R L, Dent(s), Acceptable	0,00
---------------------------------------	-------------

wing R L, Dent(s), Acceptable 0,00

No pictures to display

Bonnet, Rust, LI - Repair and paint (complete) 290,08



Wheel cover F L, Scratch(es), Acceptable 0,00

No pictures to display

Door R R, Scratch(es), Acceptable 0,00

No pictures to display

Bumper F, Scratch(es), LI - Repair and paint (complete) 211,80



Bumper R, Hole, Le - Replace and paint 651,00

