



VOLVO V70: 1H1G173

Vinnumber:	VV1BW8481F1316616	Versionname:	V70 D2 Polar 115PK
First Registrationdate:	19/08/2014	Fiscalpower:	
Expertise Mileage:	160624	Power Kw:	84
Bodytype:		Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metallic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2630
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Rear parking sensors
Cruise Control	Type of Tow bar
Steering wheel multifunctional	No Tow bar
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/60/16/96 H LightMetal			
Summer tyres:	Fr.L.	Uniroyal: 4 mm	Fr.R.	Uniroyal: 4 mm
	Re.L.	Uniroyal: 4 mm	Re.R.	Uniroyal: 4 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	1493,60
Backrest cover F L, Worn, Acceptable	0,00
<i>No pictures to display</i>	
Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00



Wing R L, Scratch(es), Acceptable 0,00

No pictures to display

Door F R, Scratch(es), Acceptable 0,00

No pictures to display

Door F L, Dent(s), Acceptable 0,00

No pictures to display

Wing F L, Scratch(es), Acceptable 0,00

No pictures to display

Bumper F, Dent(s) and scratch(es), LI - Repair and paint (complete) 254,16



Door frame R L, Dent(s), It - Spot repair 115,56



Rearview mirror housing R, Scratch(es), LI - Repair and paint (complete) 115,56



Door frame R R, Dent(s), It - Spot repair 115,56



Door R L, Dent(s), It - Spot repair 115,56



Tailgate, Scratch(es), Acceptable 0,00

No pictures to display

Luggage space cover, Scratch(es), Smart repair 110,64



Door R R, Dent(s), It - Spot repair 115,56



Rearview mirror L complete, Broken, E - Replace 192,00



Door panel R R, Hole, E - Replace 132,00



Door frame F R, Scratch(es), Acceptable

0,00

No pictures to display

Door panel R L, Hole, E - Replace

132,00

