



VOLVO V40: 1KGK402

Vinnumber:	YV1MV8481F2238528	Versionname:	1.6 D2 KINETIC
First Registrationdate:	28/04/2015	Fiscalpower:	
Expertise Mileage:	55404	Power Kw:	84
Bodytype:		Body color:	Blue
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	3626
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Rear parking sensors
Cruise Control	Type of Tow bar
Steering wheel multifunctional	No Tow bar
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Manual climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	NOT OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/55/16/91 W LightMetal				
Summer tyres:	Fr.L.	Vredestein: 8 mm	Fr.R.	Vredestein: 8 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Total cost ex VAT			295,44
Door R L, Dent(s), Acceptable			0,00
<i>No pictures to display</i>			
Wing R L, Dent(s) and scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Door F R, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Wing F R, Dent(s), Acceptable			0,00

wing R R, Dent(s), Acceptable 0,00

No pictures to display

Bumper F R, Scratch(es), It - Spot repair 115,56



Steering wheel, Scratch(es), Repair/replace (lump sum) 64,32



Bumper corner R L, Scratch(es), It - Spot repair 115,56



Alloy rim F R, Scratch(es), Acceptable 0,00

No pictures to display

Maintenance, Maintenance, P - Check 0,00

