


RENAULT CLIO: 1SKY485

Vinnumber:	VF15R240A57775802	Versionname:	0.9 ENERGY TCE 90 CORPORATE EDITION
First Registrationdate:	2/06/2017	Fiscalpower:	
Expertise Mileage:	37065	Power Kw:	66
Bodytype:		Body color:	Silver
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Petrol	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4503
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Windows electric F	Central consol F
Cruise Control	Luggage cover
Steering wheel multifunctional	Rear parking sensors
Radio multimedia	Type of Tow bar
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Manual climate control
	No Tow bar

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	185/65/15/88 T Steel			
Summer tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	1924,18
Interior, Smell, Ozone treatment	152,58
<i>No pictures to display</i>	
Bumper F, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Wheel cover R R, Deformed / Strained, E - Replace	24,00



Wing R L, Dent(s), LI - Repair and paint (complete)

390,56



Seat cover F L, Hole, E - Replace

312,00



Roof, Dent(s), LI - Repair and paint (complete)

529,20



Wheel cover F R, Scratch(es), E - Replace

24,00



Wheel cover R L, Scratch(es), Acceptable

0,00

No pictures to display

Wing R R, Scratch(es), LI - Repair and paint (complete)

246,56



Door F L, Scratch(es), Acceptable

0,00

No pictures to display

Steel rim R R, Deformed / Strained, E - Replace

75,84



Bumper R, Scratch(es), LI - Repair and paint (complete)

169,44



Door R L, Scratch(es), Acceptable

0,00

No pictures to display