



MERCEDES C COUPE: ZM8151

Vinnumber:	WDD2053401F645910	Versionname:	C 180
First Registrationdate:	26/09/2017	Fiscalpower:	
Expertise Mileage:	50098	Power Kw:	115
Bodytype:		Body color:	Black
Gearbox:	Automatic	Paint type:	Metallic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Petrol	Oil level:	OK
Maintenance:	OK	Parking lot:	1720
Maintenance:	A1 DANS 271 JOURS		
Battery functioning:	Yes		
Number of doors:	2		
Number of seats:	4		
Number head rests:	4		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

GPS storage	SD	Seats electric F L	
GPS storage		Seats electric F R	
Windows electric F		Central consol F	
Cruise Control		Front parking sensors	
Steering wheel multifunctional		Rear parking sensors	
Alarm		Type of Tow bar	No Tow bar
Radio multimedia			
Type of headlighting	Headlighting LED		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		
Level control			
Sport seats			

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

225/45/18/95 Y LightMetal			
Summer tyres:	Fr.L. Bridgestone: 7 mm	Fr.R. Bridgestone: 7 mm	
	Re.L. Bridgestone: 6 mm	Re.R. Bridgestone: 6 mm	

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT 1130,48

Bodywork, Hail damage, PDR - Hail 833,00



Door F R, Repaired, P - Check

0,00



Windscreen, Stone chip(s), Windscreen repair

117,60



Bumper F, Scratch(es), It - Spot repair

115,56



Floor covering F L, Burned, Smart repair

64,32



Seat cover F L, Worn, Acceptable

0,00

No pictures to display

Glove compartment lid, Scratch(es), Acceptable

0,00

No pictures to display