



VOLVO V40: 1LJR074

Vinnumber:	VV1MV7431G2298250	Versionname:	2.0 D2-82 BASE
First Registrationdate:	6/10/2015	Fiscalpower:	
Expertise Mileage:	59432	Power Kw:	88
Bodytype:		Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Maintenance:	26707	Parking lot:	3720
Maintenance:	OK		
Maintenance:	11 MAAND		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage	HD	Luggage cover	
GPS storage		Rear parking sensors	
Windows electric F		Type of Tow bar	No Tow bar
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/55/16/91 H Steel			
Summer tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Total cost ex VAT			211,80
Wheel cover F R, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Bumper R, Scratch(es), Acceptable			0,00

<i>No pictures to display</i>	
Wing F R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Rear bulkhead lining, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Bumper F, Scratch(es), LI - Repair and paint (complete)	211,80



Door F R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	